STATUTORY INSTRUMENTS

1961 No. 1070

FACTORIES

The Flax and Hemp (Record of Humidity) Order, 1961

Made - - - - 5*th June*, 1961
Coming into Operation 1*st July*, 1961

The Minister of Labour in pursuance of:—

(*a*) Regulation 4 of the Regulations dated the 26th February, 1906, made by the Secretary of State with respect to the processes of spinning and weaving flax and tow(a), and

(*b*) Regulation 6 of the Regulations dated the 28th August, 1907, made by the Secretary of State with respect to the processes of spinning and weaving hemp or jute, or hemp or jute tow(b), as amended by the Jute (Safety, Health and Welfare) Regulations, 1948(c),

hereby prescribes for the purposes of those Regulations the form on which readings of standardised wet and dry bulb thermometers are to be entered.

1.—(1) This Order may be cited as the Flax and Hemp (Record of Humidity) Order, 1961, and shall come into operation on the first day of July, 1961.

(2) The Order, prescribing the record of humidity for use in pursuance of the said Regulations 4 and 6 made by the Secretary of State on the 22nd July, 1938, shall cease to have effect.

2. The Interpretation Act, 1889(d), shall apply to the interpretation of this Order as it applies to the interpretation of an Act of Parliament, and as if this Order and the Order hereby revoked were Acts of Parliament.

3. For the purposes of the said Regulations 4 and 6 the form on which readings of standardised wet and dry bulb thermometers are to be entered shall be that set out in the Schedule to this Order.

Dated this 5th day of June, 1961.

John Hare,
Minister of Labour.

SCHEDULE

Form 318

Prescribed form for record of humidity in respect of Regulations for:

(*a*) Spinning and Weaving Flax and Tow, and processes incidental thereto (Regulation 4, S.R. & O. 1906 No. 177).

(a) S.R. & O. 1906/177 (Rev. VII, p. 319: 1906, p. 178).
(b) S.R. & O. 1907/660 (Rev. VII, p. 334: 1907, p. 145).
(c) S.I. 1948/1696 (Rev. VII, p. 336: 1948 I, p. 999).
(d) 52 & 53 Vict. c. 63.

(*b*) Spinning and Weaving Hemp, or Jute, or Hemp or Jute Tow and processes incidental thereto (Regulation 6, S.R. & O. 1907 No. 660); except as regards factories subject to the Jute (Safety, Health and Welfare) Regulations, 1948. (S.I. 1948 No. 1696.)

Name of Occupier.....

Address of Factory.....

Manufacture .....

Room { Number or Designation.....
Process carried on.....
Position of Thermometers.....

SEE OVERLEAF FOR TABLE OF READINGS WHICH MUST BE FILLED IN

Signature of Occupier or Agent.....

Date.....

Date	Readings of Thermometers in Degrees Fahrenheit				
Year Month	Between 10 and 11 a.m. in Flax and Tow Works and between 11 a.m. and noon in Hemp and Jute Works		Between 3 and 4 p.m. in Flax and Tow Works and between 4 and 5 p.m. in Hemp and Jute Works		If no humidity insert "None"
Day (1)	Dry Bulb (2)	Wet Bulb (3)	Dry Bulb (4)	Wet Bulb (5)	(6)
1st					
2nd					
3rd					
4th					
5th					
6th					
7th					
8th					
9th					
10th					
11th					
12th					
13th					
14th					
15th					
16th					
17th					
18th					
19th					
20th					
21st					
22nd					
23rd					
24th					
25th					
26th					
27th					
28th					
29th					
30th					
31st					

EXPLANATORY NOTE

(This Note is not part of the Order, but is intended to indicate its general purport.)

This Order prescribes the form on which readings of wet and dry bulb thermometers are to be entered in accordance with the Regulations dated the 26th February, 1906, made by the Secretary of State with respect to the processes of spinning and weaving flax and tow and the Regulations dated the 28th August, 1907 (as amended) made by the Secretary of State with respect to the processes of spinning and weaving hemp or jute, or hemp or jute tow.

The form prescribed by this Order is in substitution for that prescribed by the Secretary of State's Order dated the 22nd July, 1938, which is revoked.